

Airworthiness Directive Schedule

Engines

Continental A-50, A-65, C-75 and C-85 Series

28 May 2020

- Notes:** 1. This AD schedule is applicable to the following Continental engine series:

Engine Series:	FAA Type Certificate:
A-50 Series	E-190
A-65 Series	E-205
C-75 Series	E-233
C-85 Series	E-233

2. The Federal Aviation Administration (FAA) is the National Airworthiness Authority (NAA) responsible for the issue of State of Design Airworthiness Directives (ADs) for these engines. State of Design ADs can be obtained directly from the FAA website at http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/MainFrame?OpenFrameSet
3. The date above indicates the amendment date of this schedule.
4. New or amended ADs are shown with an asterisk *

Contents

DCA/CON/154	Fuel Pump - Inspection.....	2
DCA/CON/167	Carburettor Air Intake Housing Assembly - Inspection	2
DCA/CON/176A	Cancelled - Refer to Continental Motors Publication M-O	2
DCA/CON/179	Repaired Crankshafts - Inspection.....	2
DCA/CON/198	AVStar Fuel Servos – Inspection and Replacement.....	5
State of Design ADs listed below are available directly from the National Airworthiness Authority (NAA) websites. Links to NAA websites are available on the CAA website at http://www.caa.govt.nz/airworthiness-directives/states-of-design/ If additional NZ ADs need to be issued when an unsafe condition is found to exist in an aircraft or aeronautical product in NZ, they will be added to the list below.		
69-09-01	Eisemann Magnetos – Inspection.....	7
69-24-03	Carburettor – Inspection	7
80-06-05	Magnetos – Inspection.....	7
93-19-04	Carburettor – Inspection	7
94-05-05R1	Cylinder Rocker Shaft Bosses – Inspection.....	7

DCA/CON/154 Fuel Pump - Inspection

Applicability: All A-65, A-75, C-75, C-85, C-90, A-100, C-125, O-200, O-240 and O-300 engines with AC fuel pumps P/N 40585, 50695 and 631391.

Requirement: Inspect and renew parts as necessary per TCM SB M81-8. (FAA AD 81-07-06 refers)

Compliance: Within the next 50 hours TIS or 30 days whichever is the sooner and thereafter at intervals not exceeding 12 months.

Effective Date: 7 August 1981

DCA/CON/167 Carburettor Air Intake Housing Assembly - Inspection

Applicability: Model O-200A, S/N 256030 through to 256037 and

Models C-85, C-90, O-200 and O-240 series with carburettor air intake housing assemblies P/Ns CE11141, CE11142, 639814, 639815, 6413534 and repair kit assemblies P/N 641689 purchased after 31 August 1991 without a permanent ink stamp "CSB 93-13" located on the inside of the housing assembly.

Requirement: To prevent engine failure due to a cracked air valve in the carburettor air intake housing assembly, inspect housing assembly per TCM Critical Service Bulletin (CSB) 93-13. If the assembly meets the requirements of paragraph 2A of TCM CSB93-13, no further action is required. If the assembly meets the requirements of paragraph 2B of CSB 93-13, inspect the assembly for cracks per CSB 93-13. If cracks are found anywhere in the assembly, prior to further flight replace with a serviceable assembly. (FAA AD 93-22-05 refers)

Compliance: Within the next 25 hours TIS.

For those assemblies that meet the requirements of paragraph 2B of CSB 93-13, thereafter at intervals not to exceed 25 hours TIS.

Effective Date: 24 December 1993

DCA/CON/176A Cancelled - Refer to Continental Motors Publication M-O

Note: DCA/CON/176A mandated the part replacement requirements in Teledyne Continental SB97-6B. The AD and the SB identified certain parts to be replaced at the next and each subsequent engine overhaul. Continental Motors advised that SB97-6B is no longer active. The requirements in SB97-6B have now been incorporated into the Continental Aircraft Engine Maintenance Manual - Standard Practice for Spark Ignited Engines, Publication M-O.

Effective Date: 27 June 2019

DCA/CON/179 Repaired Crankshafts - Inspection

Applicability: Models A-65, A65-3, A65-8, A-75, A75-8, C75-12, C-85, C85-8, C85-12, C90-8FJ, C90-12, O-200, O-200-A, O-300, O-300-D, IO-360-C, E-185-4, E-225-8, O-470, O-470-K, O-470-L, O-470-R, O-470-11, IO-470, IO-470-N, IO-470-S, IO-520, IO-520-D, GTSIO-520, and TSIO-520-VB reciprocating engines, with installed crankshafts repaired by Nelson Balancing Service, Bedford, Massachusetts, USA, Repair Station Certificate No. NB7R820J, between February 1, 1995, and December 31, 1997, inclusive, as listed (by work order (W/O)) in Table 1 of this AD.

Table 1

MODEL	W/O	DATE	ENGINE S/N
A-65	1152	1/25/96	
A-65	1154	2/7/96	7187
A-65	1183	2/22/96	
A-65	1185	3/28/96	
A-65	1233	6/23/96	

A-65	1290	10/29/96	
A-65	1296	11/14/96	4933868
A-65	1299	11/19/96	
A-65	1325	3/26/97	
A-65	1326	3/26/97	
A-65	1376	4/29/97	
A-65	1438	6/17/97	5890178
A-65-3	1243	8/13/96	324993
A-65-8	1541	12/2/97	
A-65-8	1276	10/5/96	5762568
A75	1156	2/7/96	5321868
A75	1255	9/3/96	
A75	1256	9/4/96	
A75-8	1275	10/5/96	5162868
C75-12F	1293	11/4/96	3316-6-12
C85	1088	10/4/95	
C85	1092	10/18/95	
C-85	1198	4/17/96	29652-7-8
C-85	1297	11/14/96	
C-85	1352	3/10/97	
C-85	1381	4/28/97	
C-85	1391	4/19/97	
C-85	1392	4/19/97	
C-85	1484	9/4/97	28487-6-12
C-85-8FJ	1139	1/17/96	29845-7-8
C-85-8FJ	1420	5/12/97	29465-7-8
C-85-12	1031	4/6/95	
C85-12	1182	3/18/96	21596-6-12
C-85-12	1217	5/15/96	
C85-12	1265	9/12/96	14657
C-85-12	1298	11/14/96	23610-6-12
C-90-8F	1471	9/6/97	42838-1-8
C-90-12	1279	10/7/96	44747-6-12
E-185-4	1124	1/16/96	25700D-1-9
E-225-8	1505	10/28/97	35477-D-9-8-P
GTSIO-520	1208	5/7/96	210114-70H
IO-360-C	1126	12/28/95	F-51439-9-C
IO-470	1028	3/23/95	87329-R
IO-470-N	1421	5/13/97	95271-1-N
IO-470-S	1331	3/11/97	102412-2-S-I
IO-520	1174	3/4/96	
IO-520-D	1167	2/22/96	
O-200	1033	4/18/95	
O-200	1043	5/12/95	
O-200	1049	6/2/95	
O-200	1076	9/11/95	214668-27A
O-200	1104	11/21/95	213830-71A
O-200	1131	1/5/96	
O-200	1142	1/18/96	265349-R
O-200	1147	1/23/96	
O-200	1190	4/13/96	
O-200	1193	4/13/96	
O-200	1195	4/13/96	
O-200	1197	4/17/96	
O-200	1213	5/13/96	
O-200	1261	9/9/96	
O-200	1303	12/5/96	
O-200	1321	2/7/97	28115
O-200	1324	2/6/97	
O-200	1344	3/2/97	
O-200	1393	5/5/97	

O-200	1413	5/7/97	61001-5-4
O-200	1430	5/23/97	
O-200	1437	6/17/97	255759A-48
O-200	1488	9/7/97	
O-200	1506	11/18/97	
O-200	1522	11/11/97	
O-200-A	1052	6/21/95	254150-A-48
O-200-A	1085	9/29/95	
O-200-A	1120	12/29/95	253971
O-200-A	1161	2/9/96	24R-469
O-200-A	1215	5/15/96	
O-200-A	1240	8/5/96	69589-8-A
O-200-A	1254	9/3/96	6105-71-A-R
O-200-A	1264	9/12/96	
O-200-A	1356	3/10/97	
O-300	1027	3/20/95	
O-300	1042	5/12/95	34012-D-6-D
O-300	1083	9/26/95	
O-300	1096	10/23/95	464481
O-300	1137	1/17/96	
O-300	1259	9/4/96	
O-300	1387	4/22/97	
O-300	1397	4/26/97	5928-9A
O-300	1403	4/28/97	
O-300	1423	6/9/97	3834D8Z
O-300	1555	1/13/98	
O-300-A	1446	6/27/97	
O-300-D	1022	3/17/95	35110-D-6-D
O-300-D	1079	9/17/95	24276-D-0-D
O-300-D	1487	9/6/97	
O-300-D	1543	12/3/97	
O-470	1046	6/1/95	
O-470	1383	4/4/97	
O-470-11	1017	2/22/95	
O-470-11	1491	10/19/97	
O-470-11	1492	10/19/97	
O-470-11	1493	10/19/97	
O-470-11	1494	10/19/97	
O-470-F	1236	7/25/96	76956-4-F
O-470-K	1087	10/3/95	47172-6-K
O-470-L	1128	1/10/96	68681-8-L
O-470-L	1359	5/19/97	68245-8-L
O-470-L	1399	4/28/97	
O-470-R	1016	2/10/95	133087-6-R
O-470-R	1086	10/3/95	
O-470-R	1165	2/22/96	
O-470-R	1178	3/10/96	
O-470-R	1201	6/2/96	83164-1-R
O-470-R	1319	1/6/97	459408
TSIO-520-VB	1055	6/9/95	

Requirement: To prevent crankshaft failure due to cracking, which could result in an inflight engine failure and possible forced landing, accomplish the following:

a) Determine if this AD applies, as follows:

1. Determine if any repair was conducted on the engine that required crankshaft removal during the February 1, 1995, to December 31, 1997, time frame; if the engine was not disassembled for crankshaft removal and repair in this time frame, no further action is required.

2. If the engine and crankshaft was repaired during this time frame, determine from the maintenance records (engine log book), and Table 1 of this AD if the crankshaft was repaired by Nelson Balancing Service, Repair Station Certificate No. NB7R820J, Bedford, Massachusetts, USA. The maintenance records should contain the Return to Service (Yellow) tag for the crankshaft that will identify the company performing the repair. Also the work order number contained in Table 1 of this AD was etched on the crankshaft propeller flange, adjacent to the closest connecting rod journal. Because some etched numbers will be difficult to see, if necessary, use a 10X magnifying glass with an appropriate light source to view the work order number. In addition, the propeller spinner, if installed, will have to be removed in order to see this number.

3. If it cannot be determined who repaired the crankshaft, compliance with this AD is required.

4. If the engine and crankshaft were not repaired during the time frame specified in a) 1, or if it is determined that the crankshaft was not repaired by Nelson Balancing Service, no further action is required.

b) Accomplish the following:

1. Perform a visual inspection as defined in paragraph b) 2 of this AD, magnetic particle inspection, and a dimensional check of the crankshaft journals, or remove from service affected crankshafts and replace with serviceable parts.

2. For the purpose of this AD, a visual inspection of the crankshaft is defined as the inspection of all surfaces of the crankshaft for cracks which include heat check cracking of the nitrided bearing surfaces, cracking in the main or aft fillet of the main bearing journal and crankpin journal, including checking the bearing surfaces for scoring, galling, corrosion, or pitting.

Note: Further guidance on all inspection and acceptance criteria is contained in applicable Overhaul or Maintenance Manuals.

3. Replace any crankshaft that fails the visual inspection, magnetic particle inspection, or the dimensional check with a serviceable crankshaft, unless the crankshaft can be reworked to bring it in compliance with:

- i) All the overhaul requirements of the appropriate Overhaul/Maintenance Manuals; or
- ii) All of the approved requirements for any repair station which currently has approval for limits other than those in the appropriate Overhaul/Maintenance Manuals.

4. For the purpose of this AD, a serviceable crankshaft is one which meets the requirements of paragraph b) 3 i) or b) 3) ii) of this AD.

Note: Crankshafts removed from engine models IO-360, IO-520, and TSIO-520 series engines are also subject to compliance with DCA/CON/177. (FAA AD 98-17-11 refers)

Compliance: By 25 October 1998

Effective Date: 25 September 1998

DCA/CON/198 AVStar Fuel Servos – Inspection and Replacement

Applicability: All Teledyne Continental Motors (TCM) fuel injected engines fitted with a AVStar Fuel Systems, Inc. (AFS) fuel servo diaphragm P/N AV2541801 or P/N AV2541803.

Requirement: To prevent fuel servo failure which could result in loss of engine power and aircraft control, accomplish the following:

1. Review the aircraft records and determine if an AFS fuel servo diaphragm P/N AV2541801 or P/N AV2541803 from an affected production lot listed in AFS MSB No. AFS-SB6 revision 2, dated 6 April 2011 was installed in the fuel servo any time after 20 May 2010. If the fuel servo is found fitted with an affected diaphragm, replace the fuel servo before further flight.2. Fuel servos with an affected AFS fuel servo diaphragm P/N AV2541801 or P/N AV2541803 from the production lots listed in AFS

MSB No. AFS-SB6 revision 2 shall not be fitted to any aircraft.
(FAA AD 2012-03-06 refers)

Compliance:

1. Within the next 5 hours TIS unless previously accomplished.
2. From 24 February 2012.

Effective Date: 24 February 2012

State of Design ADs listed below are available directly from the National Airworthiness Authority (NAA) websites. Links to NAA websites are available on the CAA website at <http://www.caa.govt.nz/airworthiness-directives/states-of-design/>
If additional NZ ADs need to be issued when an unsafe condition is found to exist in an aircraft or aeronautical product in NZ, they will be added to the list below.

69-09-01 Eisemann Magnetos – Inspection

Applicability: All type AM-4, AM-6, LA-4, and LA-6 Eisemann magnetos installed on, but not necessarily limited to A-50 series, C-75 series, A-75 series, A-80 series, C-85 series, C-115 series, C-125 series, E-165 series and E-185 series engines.

Compliance: Before the issue of a New Zealand Certificate of Airworthiness, or at the next Review of Airworthiness (RA), whichever is the sooner, unless previously accomplished. Repetitive inspections, if required, to be accomplished at intervals not to exceed the times specified in the FAA AD.

Effective Date: 25 August 2016

69-24-03 Carburettor – Inspection

Applicability: A-65 series, A-75 series, O-200 series, C-85 series, C-90 series, C-145 series and O-470 series fitted with Marvel Schebler models MA-3-A, MA-3-PA, MA-3-SPA, MA-4-SPA, MA-4-5, MA-5, MA-4-5-AA, MA-6AA, and HA-6 carburetors with the following listed P/Ns and S/Ns installed on the Continental model engines listed in the AD.

Compliance: Before the issue of a New Zealand Certificate of Airworthiness, or at the next Review of Airworthiness (RA), whichever is the sooner, unless previously accomplished. Repetitive inspections, if required, to be accomplished at intervals not to exceed the times specified in the FAA AD.

Effective Date: 25 August 2016

80-06-05 Magnetos – Inspection

Applicability: Model A-65-8, A-75-8, C-85-8, C-90-8, O-200-A, O-300-A, -B, -C, -D; O-470-U, IO-360-KB, IO-470, IO-520-A, -B, -F; TSIO-470 and TSIO-520-T engines.

Compliance: Before the issue of a New Zealand Certificate of Airworthiness, or at the next Review of Airworthiness (RA), whichever is the sooner, unless previously accomplished. Repetitive inspections, if required, to be accomplished at intervals not to exceed the times specified in the FAA AD.

Effective Date: 25 August 2016

93-19-04 Carburettor – Inspection

Applicability: Precision Airmotive (formerly Facet Aerospace Products (formerly Marvel-Schebler)) model MA3, MA3A, MA3PA, MA3SPA, and MA4SPA carburetors, installed on Teledyne Continental A-65, A-75, C-75, C-85, C-90, C-115, C-125, C-145, O-200 and O-300 series engines.

Compliance: Before the issue of a New Zealand Certificate of Airworthiness, or at the next Review of Airworthiness (RA), whichever is the sooner, unless previously accomplished. Repetitive inspections, if required, to be accomplished at intervals not to exceed the times specified in the FAA AD.

Effective Date: 25 August 2016

94-05-05R1 Cylinder Rocker Shaft Bosses – Inspection

Applicability: Continental C-75, C-85, C-90, C-125, C-145, O-200, O-300 and GO-300 series engines.

Rolls-Royce C-90, O-200 and O-300 series engines.

Note: This AD is applicable to all engine models listed in the applicability section regardless of the type of cylinder installed (e.g. factory new cylinders, PMA cylinders, new or used, etc.).

These engines are installed on, but not limited to, American Champion 7BCM, 7CCM, 7DC, S7DC, S7CCM, 7EC, S7EC, 7FC, 7JC, and 7ECA; Cessna 120, 140, 150, 170, 172, 172A-H, and 175; Luscombe 8E, 8F, and T-8F; Maule Bee Dee M-4, M-4, M-4C, M-4S, M-4T, M-4-210, M-4-210C, M-4-210S, M-4-210T, and M-5-210C; Piper PA-18 and PA-19; Reims Aviation F172D, E, F, G, H, K; F150G, H, J, K, L, M; FA150K, L; FRA150L; Swift GC-1A and GC-1B; Univair (Erco) 415-D, E, and G; Univair (Forney) F-1 and F-1A; Univair (Alon) A-2 and Univair (Mooney) M-10 aircraft.

Effective Date: 27 September 2018